

No.	Regist	Name	Built	Year O	Year O	Scrapp	Other
	HB 85-83	Karosa C734.00	1981	1981	1990	2005	
	CV 92-23	Karosa LC736.20	1987	1987	1993	2004	
	CV 91-95	Karosa LC735.20	1987	1987	1993		klimatizace Konvekta,
	3A3 5637	Karosa C734.20	1988	1988	1993	2010	
	CVA 00-87	Karosa LC735.40	1989	1989	2002	2002	
	CVA 03-30	Karosa LC736	1990	1990	2003	2003	
	CVA 10-15	Karosa LC735.1011	1990	1990	2004	2004	
	CVA 07-77	Karosa C734.1340	1990	1990	1993	2003	
	CVA 09-10	Karosa C744.24	1991	1991	2001	2001	Vyřazen a sešrotován 2001. Obsluhoval linky v oblasti Kadaň -
	3A3 5881	Karosa C744.24	1991	1991	1999		
	CVA 09-11	Karosa C744.24	1991	1991	2001	2001	VYřazen a sešrotován 2001. Obsluhoval linky v oblasti Kadaň -
	CVA 17-86	Karosa C734.1340	1992	1992	1993		
	CVA 35-48	Ikarus E94	1996	1996	?		
	1U2 6391	Karosa C934.1351	1997	1997	2004		
	1U2 6390	Karosa C934.1351	1997	1997	2004		"SO" w 2008 r.